# **Core Inspection**

#### > Replaceable core

- Shaft is complete
- Shaft is not dismounted
- Gear hub and gear connection are not damaged
- Shaft is not deformed
- No strong rust







#### > Non replaceable core

## Not repairable

• The old shaft shows strong rust

### Not repairable

• The shaft is deformed and the wheel side joint is missing

## Not repairable

The shaft is deformed





**GKN Driveline** 

# **Core Inspection**

> Free of charge and expert disposal of non recycleable cores by GKN

- Incomplete shafts
- Broken shafts
- Destroyed and dismounted shafts
- Loose joints
- Externally strong damaged joints

#### will be disposed of free of charge!



